



United States Department of the Interior

BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT

Gulf of Mexico OCS Region
1201 Elmwood Park Boulevard
New Orleans, LA 70123-2394

March 30, 2021

Mr. David A. Carmony
EnVen Energy Ventures, LLC
609 Main Street, 3100
Houston, Texas 77002

Dear Mr. Carmony:

Reference is made to EnVen Energy Ventures, LLC's (EnVen) Right-of-way (ROW) modification application (TIMSWEB submittal ID: 207065916) received by the Bureau of Safety and Environmental Enforcement (BSEE) Pipeline Section on March 29, 2021, for Pipeline Segment Number (PSN) 19876, associated with ROW No. OCS-G 29383.

Specifically, EnVen requests a temporary cessation of operations for PSN 19876 until June 30, 2021. PSN 19876 has been out-of-service since January 29, 2020. The temporary cessation of operations is being requested due to continuing repairs to dislodge a stuck pig by utilizing a Felxi Coil system.

The table below describes the pipeline segment pertaining to the aforementioned application:

PSN	Size (NPS)	Length (feet)	Service	Origin	Termination
19876	6	17,511	Bulk Oil	Platform A Ship Shoal Area Block 227	Platform A Ship Shoal Area Block 243

Pursuant to 30 CFR 250.1000(b), EnVen's application is hereby approved subject to the following conditions:

1. The annual rental required by 30 CFR 250.1012 shall continue to be due and payable in December of each calendar year.
2. If the associated pipeline has not been returned to service and is not being used for the purpose for which the pipeline ROW grant was made by June 30, 2021 the ROW grant shall be deemed expired in accordance with 30 CFR 250.1014. As a reminder per 30 CFR 250.1010(h) the ROW holder must remove all pipeline segments and accessories associated with ROW No. OCS-G 29383 within one year of the effective date of the relinquishment or forfeiture (i.e. expiration). Furthermore, a decommissioning application must be submitted to the BSEE Pipeline Section to decommission PSN 19876 within 30 days from the effective date of the relinquishment or forfeiture (i.e. expiration).

3. If at any time prior to June 30, 2021 it is determined that the use of PSN 19876 is to be permanently discontinued, an application to decommission the pipeline and relinquish the pipeline ROW shall be submitted to the BSEE Pipeline Section.

EnVen is hereby reminded of the following since PSN 19876 was not returned to service on or before January 29, 2021:

1. Pursuant to 30 CFR 250.1006(b)(2), the subject pipeline segment must be flushed and filled with inhibited seawater.
2. Pursuant to 30 CFR 250.1003(b)(1), the subject pipeline segment must be hydrostatically tested for at least eight (8) hours at a stabilized pressure of a minimum of 1.25 times the Maximum Allowable Operating Pressure (MAOP) prior to return to service.

Sincerely,

BIMAL

SHRESTHA

Digitally signed by
BIMAL SHRESTHA
Date: 2021.03.30
16:29:12 -05'00'

(for) Stephen P. Dessauer
Regional Supervisor
Regional Field Operations